

# Latchup Test Considerations for Analog-to-Digital Converters\*

A. H. Johnston and T. F. Miyahira

Jet Propulsion Laboratory

California Institute of Technology

Pasadena, California

\*The research in this paper was carried out by the Jet Propulsion Laboratory, California Institute of Technology, under contract with the National Aeronautics and Space Administration, Code AE, under the NASA Electronics Parts and Packaging Program (NEPP).

# Outline

Basic Considerations for Latchup and Latchup Testing

Latchup Characteristics of the 9240 ADC


Identification of Latchup Regions

- Experimental technique
- Examples of latched regions
- Current distributions


Characterization Requirements for Latchup in Complex Circuits

Conclusions


## Latchup Path in a CMOS Circuit



## I-V Characteristics for Latchup



# Effect of Temperature on Latchup



# Experimental Approach

Samples Chemically Etched to Remove Top of Plastic Package

Tests Done Using Three Different Facilities

- Brookhaven
- Texas A&M
- Californium-252 (limited ion range)


Currents Continually Monitored During Testing

- Current “signatures” identify latchup
- Some tests done over extended time periods to investigate catastrophic failure

Special Diagnostic Tests Used to Determine Latchup Regions

- Thermal imaging used to locate latchup region
- Allow surface temperature to be measured

# Cross Section for Latchup in the 9240 ADC



## Equilibrium Currents During Latchup

Power Supply	Initial Current (mA)	Final Current (mA)
#1 - Digital Section	4.6	65 to 177
#2 - Analog Section	58	74 to 380



## Issues Relating to Current Detection and Shutdown


### Latchup Occurs in Two Distinctly Different Regions

- Both analog and digital regions exhibit latchup
- Latchup monitoring must include both sections
- Current limiting can alter results


### Detection Limits Are Difficult to Establish

- Wide range of currents during latchup
- Temperature, unit-to-unit variations must be considered
- Transient currents during normal operation must be allowed for

# Latchup Sites in the 9240 Analog-to-Digital Converter



## Multiple Latchup Events in the 9240 ADC



# Latchup Characterization Requirements

## Extensive Testing Is Required

- Determine various latchup paths and conditions
- Temperature and device variability can be important
- Catastrophic failure conditions must be determined

## Equilibrium Current Is a Useful Parameter

- Heating in vacuum is a potential interference
- Voltage drop in cabling must be low at high currents

## Latchup Rates Are Often Dominated by “Knee” Region

## Conclusions

Latchup in Complex Devices Is Difficult to Characterize

- Numerous latchup paths are present
- Equilibrium conditions vary widely

Current Limiting Power Supplies May Alter Latchup Results

Ions Used for Testing Must Have Adequate Range

- At least 40  $\mu\text{m}$  for devices with bulk substrates
- Surface metallization and contacts must be considered

Thermal Imaging Is a Useful Diagnostic Technique